

Runways

13R/31L: 14572 x 150 (ASPH-CONC-G)

13L/31R: 10000 x 150 (ASPH-G) 04R/22L: 8400 x 150 (ASPH-G)

04L/22R: 11351 x 150 (ASPH-CONC-G)

H4: 60 x 60 (ASPH-G) H3: 60 x 60 (ASPH-G) H2: 60 x 60 (ASPH-G) H1: 60 x 60 (ASPH) Coordinates

Latitude Longitude 40-38-23.104N 073-46-44.132W

Communications

GROUND 121.9

TOWER 123.9 (RW4L/22R;13R/31L) TOWER 119.1 (RW4R/22L;13L/31R)

ATIS 128.725 (718) 656-0956

CLNC 135.05

APP/DEP 127.4 (NEW YORK)

Navigation

Elevation 13 NM from City 13 SE

Instr Approach PRECISION

Owner/Manager

Owner PORT AUTHORITY OF NY & NJ

Manager MR AL GRASER

OR JERRY SPAMPANATO JFK INT'L - BUILDING 14 Services

Fuel 100LA Airframe Repairs MAJOR

Engine MAJOR

JAMAICA NY 11430

Phone (718) 244-3501 Fax (718) 244-3505 E-mail agraser@panynj.gov

Web site www.panynj.gov/aviation/jfkframe.H

Attended ALL/ALL/ALL
Airline Airport YES

Transportation


Food Lodging NEW YORK JOHN F KENNEDY INT'L AIRPORT FBO (Location)

PORT AUTHORITY OF NY AND NJ (NW) (718) 244-3771

QUEENS CO.

Remarks

NON-BASED CHARTER & COML ACFT OPERATORS MUST MAKE ARRANGEMENTS FOR FUEL PRIOR TO ARRIVAL; CALL 718-244-4111. FLOCKS OF BIRDS ON & INVOF ARPT. THE PANYNJ IS LESSEE OF OWNER (CITY OF NEW YORK, BUREAU OF FERRY AND AVIATION).



Taxi Diagram